

ERRATIC. STATIC TRACES, INDUCED BY PRESSURE ROLLER CHATTER,

ARE PRESENT ON BOTH EDGES 91 SIDE AND ONLY ON THE INBOARD

EDGE OF THE 9R SIDE. THESE STATIC TRACES ARE NOT SEVERE

ENOUGH TO APPRECIABLY DEGRADE THE IMAGERY. RESOLUTION GOOD

EXCEPT IN OUTBOARD CORNERS OF THE FORMAT.

END OF MESSAGE

NOSUSCIENTES EN CLASS. [] HID WATERS TO CLASS. [] HID DECK ASSISTED. HE ASSISTED TO TS (\$) C	25X1A
14 Aug 86	minhadhad